




UTTERMOST

Assembly Instruction

Item # 24268

Parts list

A	Table Top	1PC
B	Middle Support	1PC
C	Bottom	1PC



1. Take the parts carefully out of the carton, and then place them on a flat and soft surface, making sure that the parts will not be damaged

2. Place the table top (A) upside down on a flat and soft surface, then screw the Middle Support (B) into the screw holes under the bottom of Table Top (A), and then use spanner to secure tightly .

3. Place the Bottom (C) upside down and put it on the top of the Middle Support(B), And then screw bottom(C) into Middle support(B), then use spanner to secure tightly .

4. Put the table upside down and the assembly is complete.

